TABLE OF CONTENTS

1 INTRODUCTION 3

2 ROLES AND RESPONSIBILITIES 4

3 AUTHORIZATION TO USE RADIOACTIVE MATERIALS 7

4 PURCHASE OF RADIOACTIVE MATERIALS 9

5 RADIOACTIVE MATERIAL RECEIPT AND ACCOUNTABILITY 10

6 TRANSPORTING AND SHIPPING RADIOACTIVE MATERIALS 11

7 POSTING AND LABELING RADIOACTIVE MATERIAL AREAS 12

8 DOSES LIMITS AND PERSONAL MONITORING 13

9 CONTROL OF PERSONAL EXPOSURE 17

10 CONTAMINATION SURVEYS AND MONITORING 17

11 RADIOACTIVE MATERIAL INCIDENTS 21

12 RADIOACTIVE WASTE MANAGEMENT 23

13 RADIATION SAFETY PROGRAM AUDIT 27

APPENDIX 28

1 INTRODUCTION

The Marine Biological Laboratory (MBL) uses radioactive materials and radiation generating devices for research and academic purposes. The MBL is committed to maintaining radiation exposures to staff, students, and members of the general public *As Low As Reasonably Achievable (ALARA)*, and ensuring compliance with regulations set by the Massachusetts Department of Public Health's Radiation Protection Program (MRCP) and the U.S. Nuclear Regulatory Commission (NRC).

1.1 Purpose

The Radiation Safety Manual describes the procedures for personnel who use radioactive materials or radiation-generating devices in research and teaching laboratories at MBL. The Manual also complements the required Radiation Safety Training that all Radiation Workers must complete.

All

2.2 Radiation Safety Officer

The RSO is responsible for the implementation and maintenance of the Radiation Safety Program, including periodic update of the Radiation Safety

- Wear proper personal protective clothing (gloves, laboratory coat, and eye protection) whenever working with radioisotopes. All PPE should be kept inside the designated radioactive materi0(tiv1/i)-3(ra26( )uETQ3(t)8q0.00000912 0 612 792 reW* nBT

The RSO will review the requested amendment with the Authorized User. The RSO may approve simple changes in experimental protocol, purchase limits, laboratories, and users. For major modifications (new isotopes or location), the RSC Chair will at their discretion approve it or forward it the RSC for full review.

3.3 Authorization Termination

Authorization to use radiation sources terminates when the Authorized User leaves the MBL or at the Permit expiration date. The Authorized User must notify the RSO at least 30 days before leaving the MBL or terminating work with radioactive materials or radiation generating devices.

The Authorized User must ensure proper transfer of radioactive materials, devices, and records, and must complete appropriate laboratory exit

4 PURCHASE OF RADIOACTIVE MATERIALS

Any receipt of radioactive materials, whether a purchase or gratis shipment, must be approved by the RSO before shipment. The MBL must track and control all radioactive materials received to ensure that its possession limits are not exceeded.

4.1 Authorization to Receive Radioactive Materials

1. No one may order, receive, use, or bring into MBL any radioactive material without prior authorization from the RSC. This includes purchases from commercial vendors, other academic or research institutions, or transfers from colleagues or gratis shipment from commercial vendors.
2. Only Authorized Users with an approved protocol and a valid Radioactive Material User Permit are permitted to order radioactive materials.
3. All radioactive material orders must be approved by the RSO and placed through the MBL Purchasing Department.

4.2 Authorized Limits

The MBL Radioactive Material License restricts MBL to activity limits specific to the isotope in use. The radioactive material procurement and inventory control process prevents these activity limits from being exceeded.

Each Authorized User’s Permit specifies a limit of radioactive isotopes to be used in their laboratory. Requests to purchase isotopes that would result in exceeding a specific Authorized User's limit require an amendment to the User's permit and approval by the RSC.

4.3 Purchasing Radioactive Material

1. All radioactive orders must be submitted to the RSO with a completed MBL purchase order form which only includes radioactive material items.
2. The RSO will review the order to ensure the acquisition of the radioactive material will not cause MBL to exceed the licensed possession limits.
3. Purchases shall be limited to the radioactive materials and quantities specified in the Authorized User’s radioactive material protocol approved by the RSC.
4. Upon approval of purchase, the RSO will place the order with the vendor.

4.4

6 TRANSPORTING AND SHIPPING RADIOACTIVE MATERIALS

Transportation of radioactive materials is regulated by the MRCP, U.S. DOT, United States Postal Service (USPS), radioactive materials license of the destination institution, and other applicable local regulations.

The shipping of radioactive materials is regulated domestically as "*hazardous materials*" by U.S. DOT and internationally as "*dangerous goods*" by the International Air Transportation Association (IATA).

To ensure MBL complies with all national and international regulatory requirements, all transportation and shipping of radioactive materials must first be approved by the RSO.

6.1 Transporting Radioactive Material at MBL

Radioactive materials may be transported to an Authorized User in an MBL building provided that the following conditions are met:

- Radioactive material may not cross a public way without proper DOT packaging. Instead, use of the tunnel between Lille and Rowe should be used to avoid a public way.
- The radioactive material is tightly sealed in a leak-proof, shatter-resistant container.
- Verify that the external surface of the inner container is free of radiation contamination (i.e., emitted dose rate is less 2 mrem per hour).
- Place a radioactive material label on the vial that lists the radioisotope, activity, and reference date.
- Place the radioactive material inner container inside a second shatter-resistant container with adequate absorbent material to absorb all the radioactive material.
- Confirm that there is no removable contamination on the surface of the container, as determined by a wipe test.
- During transportation, the package must remain in the possession of Authorized User as authorized by the RSC to use the radioactive material.

6.2 Transfers between MBL and Other Institutions

All transfers and transportation of radioactive materials off MBL Campus must be approved in advance by the RSO. Transportation of radioactive materials in private vehicles is strictly prohibited by federal and state regulations.

1. The Authorized User must contact the RSO prior to committing to ship a sample of radioactive material.
2. The RSO will contact the other institution to obtain a copy of their radiation license and to arrange for receipt of the package.
3. The Authorized User is responsible for ensuring that the shipment is properly described.

4. The RSO will advise the Authorized User and laboratory personnel about packaging and shipping requirements.
5. The RSO will label, survey and inspect the package prior to shipment. The Authorized User is responsible for updating the inventory.
6. A commercial carrier such as Federal Express, World Courier, Inc., or United

8.1 Occupational Exposure Limits

Occupational exposures at the MBL will be maintained within the limits listed below.

	Annual Limit (mrem per year)	**ALARA Limit (mrem per year)**
Whole body	5,000	500
Skin and Extremities	50,000	5,000
Lens of Eye	15,000	1,500
Declared Pregnant Worker	500	50
Minors	500	50
Member of General Public	100	100

The major concern for occupational exposure to radiation at MBL is related to internal intake of radioactive materials. Internalization occurs when radioactive materials enter the body via a route of entry. The primary routes of entry are inhalation, absorption, ingestion, and injection.

The procedures and policies described in this Radiation Safety Manual are aimed at minimizing the effective uptake of radioactive materials.

8.2 Declared Pregnant Workers

The Nuclear Regulatory Commission (NRC) issued [illegible] limiting fetal radiation dose received as a result of a pregnant worker's occupational exposure to 500 mrem in the gestation period. 105 CMR 120 requires that lower exposure limits be imposed on declared pregnant women to control the dose to the embryo/fetu

- Secondary containers must be used to prevent spillage and contamination spread in the event that the primary container fails to contain the radioactive material.
- Spills of radioactive materials shall be contained immediately with the area decontaminated before work resumes. The Authorized User and RSO must be notified in the event of a spill.
- Wash hands thoroughly after using radioactive materials, before going on breaks, and at the end of the workday.
- Eating, drinking, smoking, or application of cosmetics in laboratories or areas where radioactive material is used or stored is strictly prohibited.
- Calibrated portable radiation survey meters shall be used to both monitor work areas and personnel. Surveys must be completed after each use of radioactive material (except of tritium).
- Wipe surveys shall be performed at least monthly in each laboratory or area using radioactive materials, and after each tritium use exceeding 10 µCi, to ensure contamination levels are below those specified by the RSO. More frequent surveys may be required in certain areas by the RSO or Authorized User,

10.1 Performing a Meter Survey

The Geiger-Mueller (GM) probe is the most common radiation detection instrument. The radiation detection causes both visual and audio responses. The survey meter detects radiation events and does not differentiate types of energies or radiation.

The GM probe is used for detecting beta emitters (e.g., P-32, S-35, and C-14). Low energy beta emitters such as H-3 are not detectable since they do not have enough energy to penetrate the window. Instead, use a liquid scintillation counter.

Geiger Mueller with Pancake Probe

Scintillation Probe

A hand-held scintillation detector absorbs radiation and emits light that is converted into a radiation measurement. A scintillation probe is used on survey meters like the Ludlum 3 for low energy photons (gamma rays e.g. I-125) and x-rays less than 40 keV). The efficiency of a low energy scintillation probe for the detection of I-125 is about 30-35%.

Procedures for Meter Survey:

1. Check the survey meter's battery by turning the meter knob to the battery test position. If the battery is sufficiently charged, the meter needle will swing to the BATTERY TEST position on the meter face. Replace the batteries if they are low.
2. Perform an operational check the first time you use the meter each day or when you suspect it may have been misused or damaged.
3. Check the calibration sticker on the side of the meter and note what the expected reading for the operational check source should be.
4. Switch the meter ON and turn the meter's multiplier switch to a setting that will measure the check source and will provide a mid-scale reading but will not cause the needle to swing beyond full scale.
    - For a Ludlum GM survey meter the multiplier knob should generally be set to the X1 position.
    - Place the probe firmly against the check source on the side of the meter and note the meter response.
    - If the observed meter response differs from the expected response by more than 20%, the meter should be considered nonfunctional and should be taken out of service.
    - Take the meter to an area away from sources of radiation and note the meter background reading.
5.

All Radiation Workers are responsible for reporting radiation incidents to the RSO. The individual Authorized User and Radiation Workers are responsible for handling a radiation incident. The RSO will oversee response to a radiation incident.

11.1 Response to a Spill

Small Spill:

Spills involving trace levels of radioactive material (10 µCi or less) and less than one liter, and without personal contamination or spread to non-posted areas, shall be cleaned by Radiation Workers under the direction of the Authorized User or the RSO. Clean up procedures for a small spill are as follows:

- Check all personnel for skin and/or clothing contamination with an operable survey instrument.
- Remove contaminated clothing.
- Decontaminate personnel and resurvey.
- Wear double gloves and personal protective clothing including protective shoe covers.
- Perform a final survey to document that the area has been successfully decontaminated.
- Do not allow personnel to return to work until area is cleared by the RSO.

Large Spill:

Spills in excess of 10 µCi, any spill resulting in personal contamination, spread of radioactive materials to non-posted areas, or volumes greater than one liter shall be handled according to the following procedures:

- Clear the area. If appropriate, survey all persons not involved in the spill and vacate the room.
- Prevent the spread of contamination by covering the spill with absorbent paper (paper should be dampened if solids are spilled), but do not attempt to clean it up. To prevent the spread of contamination, limit the movement of all personnel who may be contaminated.
- Shield the source only if it can be done without further contamination.)-30 1 267.89/F1

Authorized Users are required to complete and keep accurate records of radioactive materials using the "*Radioactive Material Receipt and Accountability"* form (see appendix). The RSO will provide appropriate radioactive waste containers to Authorized Users. Each radioactive waste container must be clearly labeled to identify the radioisotope, activity, date measured, Authorized User, waste type, and exterior survey results. All radioactivity labels must be defaced or removed from containers and packages prior to disposal in regular (non-radioactive) waste.

All radioactive wastes will be collected from the research and teaching laboratories by the RSO. The MBL maintains a Radioactive Waste Storage Facility, which is always kept securely locked when not in use. An inventory will be created for each radioactive waste container by the RSO. The RSO will manage, track, and coordinate final disposal of radioactive wastes.

Authorize Users should have a goal to reduce or eliminate radioactive waste as much practically feasible to minimize concerns to public and the environment while providing significant cost savings for the MBL.

12.1 Decay-In-Storage (DIS) Guidelines

- The MBL radioactive material license allows the MBL to use Decay-In-Storage (DIS) as a method of waste disposal.
- Radioactive material with a physical half-life of less than 90 days will be included in DIS disposal and shall be held for at least 10 half-lives.
- The primary location for DIS waste is the Radioactive Waste Storage Room in Lillie 8.
- All waste must be properly labeled and identified prior to transfer to the Main Radioactive Waste Storage Room.

c) Any containers with radiation levels at the surface that are higher than background radiation levels must be returned to the storage area for further decay or disposed of as Low Level Radioactive Waste (LLRW).
d) Evaluate the non-radioactive waste materials for other hazardous waste materials (hazardous chemicals or biohazardous). If other hazard, ensure those proper disposal procedures are followed.
e) Remove or deface any radioactive material labels prior to discarding the container.
f) Record the disposal date in the storage log for each container. Update the Radioactive Material Inventory Database, as necessary.
g) Create a survey record: container identification number, date the container was put in storage, date of disposal, radionuclide(s) disposed, survey instrument used, background measurement, measurement at the surface of each waste container, and the name of the individual who performed the disposal.
h) The record of each disposal must be kept for three years.

12.2 Low Level Radioactive Waste (LLRW) Guidelines

- Radioactive waste not treated as decay-in-storage must be disposed as LLRW via a commercial vendor or waste broker.
- All waste must be properly labeled with completed Radioactive Waste tag attached to container prior to transfer to the hot laboratory.
- If the container holds mixed waste, attach and complete a red Hazardous Waste tag that identifies the hazardous component.
- Mixed waste must comply with radioactive, hazardous waste regulations, and/or other applicable regulations.
- Biohazardous waste that is radioactive must be made non-infectious by approved methods before being packaged with radioactive waste.
- Complete a Radioactive Waste Container Inventory form upon arrival at the Radioactive Waste Storage Room. Issue the next consecutive storage number to the container or waste tag and complete the rest of the required information. The estimated date of disposal should be N/A. Update the Radioactive Material Inventory database, as necessary.
- Add the following information to the Radioactive Waste tag: storage number and date placed in storage.
- Consolidate waste into appropriate LLRW stream (see below): Dry Active Waste (DAW) for Compaction, DAW Non-Compactable, Liquid Scintillation vials, or Bulk Liquids
- Sealed sources must be stored separately and cannot be combined with the LLRW waste.

12.5 Uranyl Acetate Waste

Uranyl acetate is regulated differently from other radioactive materials used at the MBL. Any researcher can purchase uranyl acetate directly from the vendor without a radioactive materials license. However, uranyl acetate waste must be disposed of as radioactive waste.

There should be no generation of mixed waste with uranyl acetate without the prior

APPLICATION FOR PERMIT TO USE RADIOACTIVE MATERIALS

The MBL must maintain a permanent record of each individual who uses radioactive materials under the

APPLICATION FOR PERMIT TO USE RADIOACTIVE MATERIALS

PRINCIPAL INVESTIGATORS, COURSE DIRECTORS AND INSTRUCTORS who supervise the use of radioactive materials must provide the following information to the Radiation Safety Officer and the MBL Radiation Safety Committee. Prior approval by the MBL Radiation Safety Committee is required for all work involving the use of licensed radioactive materials in MBL.

ISOTOPE(S)	ANTICIPATED TOTAL USAGE (ACIVITY)	MAXIMUM INVENTORY	AMOUNT USED PER EXPERIMENT	CHEMICAL / PHYSICAL FORM

DESCRIPTION OF PROPOSED RESEARCH (*use additional sheet if necessary*).

List locations where you plan to use radioactive materials (Building / Room):

RESEARCH PIs ONLY:

Please list all the personnel you will be working with or supervising while conducting these experiments:

Have you had previous experience conducting such or similar experiments?

YES NO

List the Make, Model, and Serial Number of any portable survey meter(s) you have brought to the MBL. *Survey meters are required when research involves the use of gamma emitters or beta emitters with Emax > 0.2 MeV. Survey meters must be calibrated annually.*

SPECIAL RADIATION CONCERNS / ADDITIONAL INFORMATION (if appropriate)

Will radioactive materials be used with animals? **YES NO**

If yes, please include the Protocol Number from the IACUC.

Will radioactive material be used with any biohazardous materials? YES NO

If YES, please include name of organism_____ and IBC Protocol #: ____

Will radioactive material be mixed with any hazardous chemicals? YES NO

If yes, please include the name of the chemical: _____

I have received, read and understood the MBL Radiation Safety Manual. I agree to abide by the requirements regarding the use of radioactive materials at the MBL.

PRINT NAME: _____

SIGNATURE: _____ **DATE:** _____

RADIOACTIVE MATERIALS PACKAGE RECEIPT FORM

This Form must be completed by an individual authorized to directly accept shipment of radioactive materials by the Radiation Safety Committee. Return the completed form and the shipping paper to the Radiation Safety Officer (RSO) at Lillie Room 203 or safety@mbl.edu. Record the following information (all information is required).

Purchase Order Number:	
Vendor:	
Radioisotope:	
Activity Received (µCi):	
Principal Investigator (PI):	
Exposure; CONTACT (R/hr):	
Exposure; I METER (mR/hr):	
Wipe Test (dpm):	
Package Type (LQ; WI; YI; YII):	
Receipt Date:	
Receipt Time:	
Name of Person Receiving:	
Signature:	

1. Exposure is measured with a survey meter equipped with a Geiger-Mueller (GM) pancake probe in a low background area.
2. Record the highest exposure at the surface of the package and at 1 meter (3 feet) from the surface of the package.
3. A wipe test is conducted by wiping a filter paper over a 300 cm^2 (7”x7”) area of the package exterior. Count the wipe test with a liquid scintillation counter.
4. Package Type:
   - **LIMITED QUANTITY (LQ)** has a **UN 2910** label.
   - **WHITE I (WI)** has a white diamond with red “I”.
   - **YELLOW II (YII)** is a yellow and white diamond with red “II”

***Please notify the RSO at (508) 289-7424 immediately if a package appears damaged, leaking, or the wipe test is > 3000 dpm*.**

RADIOACTIVE MATERIAL ACCOUNTABILITY RECORD

1. RECEIVING RECORD

AUTHORIZED USER: **SIGNATURE:** **LAB/ROOM:**

Upon completion of work, return form to the Radiation Safety Officer. Retain a copy for records.

SIGNATURE OF AUTHORIZED USER **DATE COMPLETED**

DECLARATION OF PREGNANCY

Name of Employee:	

RADIATION SURVEY REPORT

S	**DATE:**

RADIOACTIVE WASTE CONTAINER INVENTORY

BUILDING:	ROOM:	AUTHORIZED USER:

WASTE TYPE: **LIQUID** **DAW (SOLID)**

RADIATION SAFETY PROGRAM AUDIT CHECKLIST

AUDIT REPORT NO.: _____ **LICENSE NO.:** _____

Expiration Date: _____
Audit of activities at (Address):

Date of this Audit: _____

Summary of Finding nscfrU27uatioress):

MATERIALS

Isotopes, quantities, and use as authorized on license

RECEIPT AND TRANSFER OF RADIOACTIVE MATERIAL (INCLUDES WASTE DISPOSAL)

A. Procedures describe how packages are received and by whom [ ] Y [ ] N
B. Written package opening procedures established and followed [ ] Y [ ] N
C. If package shows evidence of degradation, monitor for
D.

PERSONNEL RADIATION PROTECTION

A. ALARA considerations are incorporated into the Radiation Safety Program [ ] Y [ ] N

B. Adequate documentation of determination that unmonitored occupationally individuals are not likely to receive >10% of allowable limit [ ] Y [ ] N [ ] N/A

OR

C. External dosimetry provided and required [ ] Y [ ] N [ ] N/A
   1. Supplier Frequency
   2. Supplier is NVLAP-

POSTING AND LABELING

A. "Notice to Workers" is posted [ ] Y [ ] N
B. License documents are posted, or a notice indicating where documents can be examined is posted [ ] Y [ ] N
C. Other posting and labeling [ ] Y [ ] N

Remarks:

RECORD KEEPING FOR DECOMMISSIONING (if needed) [ ] N/A

A. Records of information important to the safe and effective decommissioning of the facility maintained in an independent and identifiable location until license termination [ ] Y [ ] N
B. Records include all information [ ] Y [ ] N

Remarks:

BULLETINS AND INFORMATION NOTICES

C. Receipt of Bulletins, Information Notices, Newsletters, etc. [ ] Y [ ] N
D. Appropriate action taken in response to Bulletins, Information
E. Notices, etc. [ ] Y [ ] N

Remarks:

SPECIAL LICENSE CONDITIONS OR ISSUES [ ] N/A

A. Review special license conditions or other issues, and describe findings:
B. Problems/deficiencies identified at MBL facilities other than at audit location:
C. Evaluation of compliance:

CONTINUATION OF REPORT ITEMS [ ] N/A

(If more space is needed, use separate sheets and attach to report.)

PROBLEMS